

1A2 400D

Issue 14

Line Card

Disconnected
end of diode
insulated with
heat shrink tubing

Orange Jumper
to -24 Batt
for the modification
to allow
ring-up detection
without grounding

Diode on
Component
Side:
Disconnected
at top edge

-24
Batt

